

Abstract

A method of manufacturing a Coriolis flowmeter for the measurement of a process material requiring an ultra high level of purity. This is achieved by forming the entire flow path of the Coriolis flow meter from a PFA plastic material that does not transfer ions from the Coriolis flowmeter to the process material flowing through the flowmeter.

2025-09-09 10:00:00